RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No128099

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080108-4

RECEIVED FROM

DATE REC'D. 1-16-57

P. O. NO 69075

VENDOR PACKING SLIP NO. 10590

ACCT. OR W. O. NO.

S. O. NO.

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322	000000	10083	0	0	00	00	02

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	730163-69 BOX CONNECTOR CANNON AN [illegible] 3102A-16-11P	10 ✓		

RECEIVED BY

INSPECTED BY Dmq

DATE 1/17/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No128100

RECEIVED FROM

DATE REC'D. 1-16-57

P. O. NO. 69075

VENDOR PACKING SLIP NO. 10590

ACCT. OR W. O. NO.

S. O. NO.

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.
322	000000	10084	0	0	00	00	02

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	730163-74 CANNON PLUG AN 3106E-20-27 P.X.	10 ✓		

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080108-4

RECEIVED BY

INSPECTED BY Dmq

DATE 1/17/57

REJECTS RETURNED ON SHIP. MEMO NO.